2nd Part

TOL code 014-14-000029
SH: 12 Works

M.A.R. 57 (Rule 116)

Measurement Book

TSW EE/Dn/241/13-14 dt 30.10.2013

No. C/09

166173

Serial No.....

Name of work. Minor Maintenance in Bagalagunte Ward 14. 2nd & 10th Cross (Laying)

From.....To.....

Name of Contractor or nature of Agency. Thayamma W.O. No 24 Bedar Colony Bagalagunte

Date of commencement of work. WON EE/Dn/241/2013-14 dt 9/1/2014

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Specification of laying of SFU and Stone slab for Road in Stony location for Cover Berm in laying dusty of the Road in Sand Gravelly or on Cover Berm and in layers as directed by Engl Note on site Not exceeding 150 mm. Overall mean depth Not Pwo 1664/11 to		CMB no 1665/10-11		0.252.36/14	1127.60 Sq	284561/-
2	Laying B-S Slab of thickness and Stacking SH Cycle Qty mean depth Not Pwo 1664/11/2 MB no 1665/10-11				SD-14	1125.50 Sq	562755/-

Scanned by CamScanner

Scanned by CamScanner



MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
3	Refixing Stone Slabs of chain on Double ಮಾಡಿದ 13 ½ Cycle					1125-00	7878/-
	Over Wicket Shed ②						
							34871/-
	Certified						
	(1) Work done is Satisfactory						
	(2) Measurement recorded from Workbook						
	(3) Certified that no other claims from the Contractor						

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಪೂರ್ವ ವಿಭಾಗ
ಮಾರತಹಳ್ಳಿ, ಬೆಂಗಳೂರು

Serial
Name
Name
Date
Date
1